



DESCRIPTION:	ST041 Sludge Hopper Inspection & Service	FREQUENCY:	
LOCATION:	ST041 Goodna STP	STANDARD JOB No.:	

SCOPE
Complete inspection and service of sludge hopper
NOTES
Scissor lift required
MINOR SERVICE
Check that grease has not hardened in grease lines to Clam Shell Gates conical outlets.
Apply ELP2 grease to Clam Shell grease lines.
Ensure load cells are free from build-up of dirt and debris.
Inspect Pneumatic rams for leaks and general appearance, includes mountings.
INTERMEDIATE SERVICE
Check that grease has not hardened in grease lines to Clam Shell Gates conical outlets.
Apply ELP2 grease to Clam Shell grease lines.
Ensure load cells are free from build-up of dirt and debris.
Inspect Sludge Hopper and structure for defects.
Inspect Pneumatic rams for leaks and general appearance, includes mountings.

Doc Id: FOR467 Active Date: 18/10/2022 Revision 1 Tyson Craig Printed: **Printed copies of this document should be verified for currency against the published electronic copy.** Owner Page 1 of 1

Note: