

 DESCRIPTION:
 6 Monthly Zone 1 Lubrication Maintenance
 FREQUENCY:
 6 Monthly

 LOCATION:
 ST32 Gibson Island WRP
 STD JOB ID:
 LTS063

Grease and Oils Required	Maintenance Group
Castrol AP3 Grease	Main Pump Station
Castrol EPL2 Grease	Dry Well
Castrol Alpha SP680	Wet Well and Screens
Castrol Mollub Alloy 936SF Open Gear Grease	Grit Dredger
	Step Screens and Conveyors
	Screening Bins
	Inlet Valves
Reference	
Main Pump Station	
Lubricate pump motor bearings with AP3 Grease w	ith 3 - 5 shots from a hand-operated grease gun.
Recommendation: Drive end 60 grams. Non-Drive	
Note: Motor must be running and bearings warm (a	
troto moto mast so raming and soamige mann (c	actionial operating temperature)
Grit Dredger	
Lubricate all bogey wheel bearings with EPL2 Grea	Δ20
	bearings of one side of the bridge. 1 shot per nipple.
Do not allow the bridge to travel further than approx	
	n, grease the wheel bearings of the other side of the bridge
	per nipple. Note:- clam gate must be moving while greasing
Lubricate pump and motor bearings with 4 shots of	AP3 grease.
Drain primary and secondary gearbox oils and refill	with Alpha SP680.
	with Alpha SP680.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move	with Alpha SP680.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins	with Alpha SP680. ed to LTS060 to be done monthly.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C	with Alpha SP680. ed to LTS060 to be done monthly. pen Gear Grease
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins	with Alpha SP680. ed to LTS060 to be done monthly. pen Gear Grease
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease)	with Alpha SP680. ed to LTS060 to be done monthly. ppen Gear Grease e nipple located below gearbox)
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease) Step Screens Transverse Conveyors (3 off) (Months)	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320)
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease)	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320)
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease) Step Screens Transverse Conveyors (3 off) (Months)	with Alpha SP680. ed to LTS060 to be done monthly. ppen Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) Grease
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease) Step Screens Transverse Conveyors (3 off) (Mac Lubricate screw conveyor packing grease with AP3)	with Alpha SP680. ed to LTS060 to be done monthly. ppen Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) Grease
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Multiple Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessions.)	with Alpha SP680. ed to LTS060 to be done monthly. ppen Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) Grease essary.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Machine Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary Screens Incline Conveyors (3 off) (Mevaled)	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P)
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Machine Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyo	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Machine Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary Screens Incline Conveyors (3 off) (Mevaled)	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Multiple Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Check gearbox oil levels.	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Machine Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary screens Incline Conveyors (3 off) (Mevalubricate screw conveyor packing box with AP3 Greater Check gearbox oil levels. Top up with SP680 if necessary screens No. 1,2&3	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease essary.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Machine Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with SP680 if necessary conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with SP680 if necessary con	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease essary.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been moved. Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF Clubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Malabricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary screens Incline Conveyors (3 off) (Mevallubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Mevallubricate screw conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary street Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary street Screen drive with 4 shots of EPL2 greater Screen drive with 4 shots of EPL2 greater Screen Screen drive with 4 shots of EPL2 greater Screens No. 1,2&3	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease essary.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been move Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF C Lubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Machine Lubricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Meva Lubricate screw conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with SP680 if necessary conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary conveyor packing box with SP680 if necessary con	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease essary.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been moved. Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF Clubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Malabricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary screens Incline Conveyors (3 off) (Mevallubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Mevallubricate screw conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary street Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary street Screen drive with 4 shots of EPL2 greater Screen drive with 4 shots of EPL2 greater Screen Screen drive with 4 shots of EPL2 greater Screens No. 1,2&3	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease essary.
Drain primary and secondary gearbox oils and refill Grit Pump Stuffing Box greasing has been moved. Valves near Screens Bins Lubricate valve spindles with Mollub Alloy 936SF Clubricate Dezurik valve with EPL2 Grease. (grease Step Screens Transverse Conveyors (3 off) (Malabricate screw conveyor packing grease with AP3 Check gearbox oil levels. Top up with SP680 if necessary screens Incline Conveyors (3 off) (Mevallubricate screw conveyor packing box with AP3 Greater Screens Incline Conveyors (3 off) (Mevallubricate screw conveyor packing box with AP3 Greater Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary street Screens No. 1,2&3 Check gearbox oil levels. Top up with SP680 if necessary street Screen drive with 4 shots of EPL2 greater Screen drive with 4 shots of EPL2 greater Screen Screen drive with 4 shots of EPL2 greater Screens No. 1,2&3	with Alpha SP680. ed to LTS060 to be done monthly. Open Gear Grease e nipple located below gearbox) eva Shaft Less Screw Conveyors Model U320) o Grease essary. Shaft Less Screw Conveyor Model U320P) ease essary.

Doc Id:FOR819Active Date:14/3/2017Urban Utilities ConfidentialOwnerMatthew DellawayRevision:2Page 1 of 1

Note: Printed copies of this document should be verified for currency against the published electronic copy.